



PHOTO ①

Ⓐ

Ⓑ





A

B

Photo ②



RUF

RUF

C

d

d


d

REV. S. SAW TOWARD'S  
RIVER SIDE

RUF

PHOTO 3





VARIOUS ROAD  
FAULTS DISRUPT  
THROUGH WITH

Photo 4

VARIOUS DISCHARGE  
GULLIES THROUGH WARD TO RIVER



